



Technical Service Information Bulletin

January 10, 2006

Title:

TRUNK WILL NOT CLOSE

Models:

'06 GS 300 & GS 430

BODY
B0001-06

Introduction Customers may complain that the trunk closer motor is not operating and the trunk will not close. An improved trunk closer motor has been developed to correct this condition.

- Applicable Vehicles**
- **2006** model year **GS 300** and **GS 430** vehicles produced **BEFORE** the Production Change Effective VINs shown below.

Production Change Information

MODEL	ENGINE	POWERTRAIN	PRODUCTION CHANGE EFFECTIVE VIN
GS 300	V6	—	JTHBH96S565026215
		AWD	JTHCH96S660013636
GS 430	V8	—	JTHBN96S465010757

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
640201	R & R Trunk Closer Motor	0.3	64650—50020	9A	99

Applicable Warranty*:

This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.




**Parts
Information**

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
64650-50020	Same	Closer Assembly, Luggage Door	1

**Parts
Identification
Method**

The supplier code on the part label should be “5J21” or higher.

**Repair
Procedure**

Replace the trunk closer motor assembly.

Refer to the Technical Information System (TIS), 2006 model year GS 300 or GS 430 Repair Manual: *Engine Hood / Door: Luggage Compartment Door: On-vehicle Inspection, Removal, and Adjustment.*