

New features are:

Category	Vehicle	System	Function	Content
Vehicle Coverage	-	-	-	Covered all the models by January 2019.
Functional Improvement	ECB-R vehicle	ABS/VSC/TRC(TRAC)	Air Bleeding	Change the screen to display at the time of error.
Functional Improvement	-	Engine	Evap System Check	Modified the following because there was no enough information of operating condition for some vehicles.,/br> - Added "Battery voltage is more than 10.5V" on the operating condition confirmation screen. - Deleted "HINT" from the operating condition confirmation screen. - Added the information about wait for 5 minutes during IG OFF on the error screen. - Added "HINT" on the error screen.
Functional Improvement	Diesel vehicle	Engine	Injector Compensation	Changed entry field of injector compensation code entry screen as imprinted array of ID code on the head portion of the injector.
Functional Improvement	-	Engine	Data List	Decreased the number of display items on Primary Group for some vehicles to increase the update rate of Data List.
Functional Improvement	-	Engine	Data List Active Test	Increased the number of display digits after the decimal point because the display value did not change by pressing the arrow button by performing some Active Test which has small amount of change for the indicated value. Accordingly, increased the number of display digits after the decimal point of items for the Data List which outputs the current value.
Functional Improvement	AVANZA (201609-)	IMM	Key Registration	Changed so that key registration could be performed using the utility.
Functional Improvement	AVANZA (201609-)	IMM	Transponder Code Erasure	Changed so that transponder code erasure could be performed using the utility.
Functional Improvement	with Auto Location Type Tire Pressure Warning System	Tire Pressure Monitor	ID Registration/Tire Position Write	Added new Utility "ID Registration/Tire Position Write". Description: This Utility registers transmitter ID, the number of tires with transmitters and the tire position.
Bug Fix	LAND CR PRADO	Engine	NOx Sensor Check	Fixed the bug; Solved the problem that displayed check result between Fr- Nox sensor and Rr-Nox sensor were the reverse in the specification of "NOx Sensor Check" Utility.
Bug Fix	LC500 LS500	Engine	Fuel Consumption	Fixed the bug; Solved the problem that items of "9th Gear Rate" and "10th, > Gear Rate" were not displayed correctly.
Bug Fix	LC500 LS500	Engine Transmission	Data List	Fixed the bug; Solved the problem that values of "9th" and "10th" were not displayed correctly in the Data List for "Shift Status".
Bug Fix	LC500 LS500	Transmission	Active Test	Fixed the bug; Solved the problem that changing to "9th" is not working in the Active Test for "Control the Shift Position".
Bug Fix	-	Stop and Start	DTC	Fixed the bug; Changed the display name of DTC listed on the following. - "ECU Internal Error" -> "ECU Malfunction (Starter Circuit)" - "Starter Circuit Stuck On" -> "ECU Malfunction (Low Voltage Signal) Stuck On"
Bug Fix	-	Hybrid Control	Data List	Fixed the bug; Changed the display name of Data List listed on the following. - "Sports Mode" -> "M or S Shift Position Signal"
Bug Fix	-	Stop and Start	Data List	Fixed the bug; Changed the number of digits after the decimal point for "Integrated Current" of Data List to modify the error that a value is not displayed correctly.
Bug Fix	TUNDRA, SEQUOIA, AVALON	SRS Airbag	Vehicle Control History	Fixed the bug changed plus and minus of recorded values that occurred on the following parameters. -Yaw G Sensor Installation Informatior -Longitudinal G Sensor Signal -Lateral G Sensor Signal
Bug Fix	with Pedestrian Protection System	Pedestrian Protection	DTC	Fixed the bug; Solved the problem that name of DTC U0125 is not displayed correctly.