

# DEALER STOCK VEHICLE INSPECTION GUIDE




The following inspection guide will help you determine the status of the vehicles in dealer stock. Make sure to follow all steps provided for the vehicle you are inspecting.

If you have any questions regarding the information provided, please contact your region representative.

The following vehicles may be released from dealer stock.




The following vehicles need to be inspected to determine if they can be released or must be held in dealer stock.



The following vehicles must be held in dealer stock.



Please note, vehicles produced later may have a white paint mark on the accelerator pedal. If confirmed, the vehicle may be released from dealer stock.



Created by Quality Compliance  
Version 1

\* The '05 – '10 Avalon, '07 – '10 Camry, '09 – '10 Corolla, '08 – '10 Highlander, '09 – '10 Matrix, '04 – '09 Prius, '05 – '10 Tacoma, '07 – '10 Tundra and '09 – '10 Venza are included in the Safety Recall for potential floor mat interference with the accelerator pedal. Vehicles may be delivered provided that:

- The driver's floor mat and front passenger floor mat are removed from the cabin of the vehicle (the mats may be placed in the trunk). If the floor mat is placed in the trunk, the customer must be advised of the Consumer Safety Advisory.
- or
- The floor mats are semi-permanently secured to the vehicle using Plastic Fasteners (Swiftlatch®) or Self Locking Nylon Tie-Wraps. *NOTE: All Weather Floor Mats are on Stop Sale and should not to be installed prior to vehicle delivery.*